

TIPOS DE CABEÇOTES PARA CADA MODELO DE MÁQUINA

Head assortment	FP / UFP	HPR 50	HUR 50	HPI 50	HUI 50	HUIL 50	HUIT 50	HUF 50	HUFT 50	HOI 50	HOIL 50	HOIT 50	HPFL 50	HV/V
WH(Q) 10 CNC	✓	✓												
WH(Q) 105 CNC		✓	✓											
WHN 110 (Q, MC)		✓	✓											
WHN 130 (Q, MC)		✓	✓		✓						✓			
WHN(Q) 13/15 CNC	✓	✓	✓		✓	✓		✓			✓			
WHR 13 Q	✓	✓	✓		✓	✓		✓			✓		✓	
MAXIMA I / II		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		✓	✓
WRD 13 (Q)	✓	✓	✓		✓	✓		✓			✓		✓	
WRD 130 / 150 (Q)		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		✓	✓
WRD 170 (Q)		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
WRD 180 H		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
GRATA		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓		✓	✓
WHT 110 (C)		✓	✓		✓	✓					✓		✓	
WHT 130 (C)		✓	✓		✓	✓	✓	✓	✓		✓		✓	
WVM 2600/3600 T							✓		✓	✓				

